CLINTON RIVER SPILLWAY - Near Shore Site n19

Z scores of indicator measurements at site n19 relative to all near shore sites
(Actual values for each indicator are given above each bar)
See page 1 for color key, value units, abbreviations, and critical values.